

# 安全评价报告信息网上公示

	项目名称	呼伦贝尔蒙西煤业有限公司安全现状评价报告		
	行业类别	第一类 1a	报告提交时间	2022.9.15
项目概况	项目简介	<p>呼伦贝尔蒙西煤业有限公司（以下简称“蒙西煤矿”）隶属于沈阳焦煤股份有限公司呼伦贝尔市分公司，位于陈旗煤田宝日希勒勘探区东部详查区的西北部，行政区划隶属于内蒙古自治区呼伦贝尔市海拉尔区谢尔塔拉镇。矿井核定生产能力 1.8Mt/a，安全生产许可证、采矿许可证、营业执照齐全有效，矿主要领导持证上岗，为合法正常生产矿井。</p> <p>蒙西煤矿 2005 年 5 月 28 日动工兴建，2007 年 9 月 30 日建成正式投产，最初设计生产能力为 0.6Mt/a，服务年限 55.4 年；2010 年生产规模变更为 1.2Mt/a，2018 年 1 月 15 日由内蒙古自治区煤炭工业局局务会研究决定（内煤函字〔2018〕9 号），同意该矿生产能力由 1.2Mt/a 核增至 1.8Mt/a。</p>		
安全评价项目参与人员	项目评价组长	王晓华	技术负责人	孔凡平
	过程控制负责人	唐晓娟	报告编制人	王晓华 牛胜利
	报告审核人	李茂刚	安全评价师	张会平 李耀 王飞 岳泰 王松森 朱胜利 牛胜利
	注册安全工程师	孔凡平、唐晓娟、张会平、王飞、朱胜利、牛胜利	技术专家及技术人员	——
评价活动主要信息	安全评价类型	现状评价		
	到现场开展评价工作人员	王晓华、牛胜利、朱胜利		
	到现场开展评价工作时间及主要任务	2022.8.9 了解项目的基本情况、对现场进行勘验；2022.8.23 对现场整改情况进行了复查。		

现场照片





		 A photograph showing two male workers in a factory or industrial setting. They are wearing dark blue work jackets with reflective stripes and red hard hats. They are standing next to large, complex industrial machinery, which includes green and blue components. The worker in the foreground is looking towards the camera, while the one in the background is looking down at the equipment.
	备注及其他信息	无