


安全评价报告信息网上公示

项目概况	项目名称	中国石油天然气股份有限公司内蒙古包头销售分公司校园路宏昌加油站安全现状评价报告		
	行业类别	石油加工业	报告提交时间	2026.2.3
	项目简介	<p>中国石油天然气股份有限公司内蒙古包头销售分公司校园路宏昌加油站于 2007 年 08 月 27 日成立，位于内蒙古自治区包头市昆都仑区校园南路南侧（宏昌学校附近），法定代表人为卢俊鹏，该加油站的危险化学品经营许可证有效期限为 2023 年 02 月 24 日至 2026 年 02 月 23 日。许可范围：汽油、柴油的零售。</p> <p>加油站加油区设置 2 台四枪加油机。设置直埋地下卧式双层 SF 油罐 4 个，其中 3 个 30m³汽油罐，1 个 30m³柴油罐，$V=30m^3 \times 3+30m^3 \times 1=120m^3$，总容积为 120m³，折合容积为 105m³（柴油罐容积折半计算），加油站与北方燃气 CNG 加气站合建，两者隶属于不同的公司，经营场所共用，储气区与储油区分开布置，安全防火间距符合《汽车加油加气加氢站技术标准》（GB50156-2021）表 5.0.13-2 的相关要求，CNG 加气站采用 CNG 长管拖车作为气源，站内设 6 组单瓶 0.92m³ 的固定储气瓶组，总容积为 5.52m³，拖车总容积不超过 24m³，根据《汽车加油加气加氢站技术标准》（GB50156-2021）第 3.0.15 条规定属于二级加油加气合建站，该站设置洗车房，该站设置电动汽车充电设施，该站设置光伏发电设施。。</p>		
安全评价项目参与人员	项目评价组长	刘全进	技术负责人	邹方永
	过程控制负责人	唐晓娟	报告编制人	刘全进
	报告审核人	张会平	安全评价师	徐忠臣 臧怀壮 刘红岩 郭晓娟 康惠花
	注册安全工程师	刘全进、刘红岩、康惠花、唐晓娟、邹方永	技术专家及技术人员	——
评价	安全评价类型	安全现状评价		

活动 主要 信息	到现场开展评价工 作人员	刘全进、刘红岩
	到现场开展评价工 作时间及主要任务	2025.12.24, 了解项目的基本情况、对现场进行勘验。
	现场照片	 <p>The first photograph shows a wide asphalt parking lot with several cars parked. In the background, there are several multi-story residential or commercial buildings under a clear blue sky. The second photograph shows a white building with a red stripe and the text 'CAR SERVICE CENTER' on its roof. A white car is parked in front of it, and a yellow arrow is painted on the ground pointing to the right. The third photograph shows a gas station with a red and white canopy. A sign for 'CNOOC' is visible on a building in the background. The ground is dark asphalt with some snow patches.</p>



备注及其他信息

无