

安全评价报告信息网上公示

项目概况	项目名称	中国石化销售股份有限公司内蒙古包头石油分公司青北加油站安全现状评价		
	行业类别	石油加工业；化学原料、化学品及医药制造业	报告提交时间	2024.3.1
	项目简介	中国石化销售股份有限公司内蒙古包头石油分公司青北加油站，许可范围：汽油、柴油。该站位于内蒙古自治区包头市 110 国道南青北路西侧（北新街道口处）。 该站现设有埋地双层储油罐 5 台，其中汽油罐 3 台，柴油罐 2 台，单罐容积均为 20m³。 依据《汽车加油加气加氢站技术标准》（GB50156-2021）中 3.0.9 条款加油站等级划分规定，柴油罐总容积可折半计入油罐总容积，因此折算成油罐总容积为 80m³，该站属三级汽车加油站。		
安全评价项目参与人员	项目评价组长	王晓华	技术负责人	邹方永
	过程控制负责人	唐晓娟	报告编制人	王晓华
	报告审核人	张会平	安全评价师	刘全进 臧怀壮 郭雨清 田志兴
	注册安全工程师	张会平、唐晓娟、邹方永、刘全进、郭雨清	技术专家及技术人员	——
评价活动主要信息	安全评价类型	安全现状评价		
	到现场开展评价工作人员	王晓华、田志兴		
	到现场开展评价工作时间及主要任务	2024.1.22，了解项目的基本情况、对现场进行勘验；2024.1.23 复查。		
	现场照片			





		 A photograph showing three individuals standing in front of a building entrance. On the left is a man in a black jacket and glasses. In the center is a woman in a blue winter jacket. On the right is a man in a grey jacket and glasses. The ground is covered in snow. The building has a sign that reads '晋北加油站' (Jinbei Gas Station) and another sign with a red heart logo. Above the entrance is a large red LED display showing various numbers and text.
	备注及其他信息	无